

Lot No	Description
9	Jones & Shipman 540 Surface grinder Serial Number: 1852W37Please Note:PoWRA: A 'point of work' risk assessment must be completed, reviewed and approved on site by the Auctioneer prior to any work commencing on this lot Guarding: This item does not comply with current health and safety standards regarding guarding and will require risk assessment and possible remedial action prior to first use. The purchaser should satisfy themselves as to the safety of the item in accordance with the intended use and set up and that it meets current Health & Safety Regulations, in particular PUWER Regulations, prior to being put into use. The purchaser will be required to sign an undertaking confirming their agreement.
24A	Hydrovane Receiver mounted screw compressor with A.J Metal Products air receiver and CompAir Blizzard air dryer Please Note: PoWRA: A 'point of work' risk assessment must be completed, reviewed and approved on site by the Auctioneer prior to any work commencing on this lot Pressure Systems WSE - This item has no record of Written Scheme of Examination (WSE). The purchaser must ensure a WSE is carried out by a competent person prior to first use. The purchaser will be required to sign an undertaking confirming their agreement. This Lot cannot be collected until 12noon on Wednesday 19/08/2026
27	Unbranded Mobile gantry crane SWL 1 tonne with Euro 1 tonne hoist Please Note:LOLER: This lot has no record of Thorough Examination. The purchaser must ensure a Thorough Examination is carried out by a competent person prior to first use. The purchaser will be required to sign an undertaking confirming their agreement.
30	Status Maxi - Check Notsa Co-ordinate measuring machine Serial Number: 1309Please Note:PoWRA: A 'point of work' risk assessment must be completed, reviewed and approved on site by the Auctioneer prior to any work commencing on this lot
60	Metal fabricated work bench 180cm x 62cm x 78cm Please Note: Manual Handling: Please ensure sufficient & suitable resource / handling aids are used to manage this uplift. LSH employees / representatives will not be able to assist.
61	Metal fabricated work bench 180cm x 62cm x 78cm Please Note: Manual Handling: Please ensure sufficient & suitable resource / handling aids are used to manage this uplift. LSH employees / representatives will not be able to assist.
63	Wooden topped metal framed workbench with vice 30cm x 140cm x 90cm Please Note:Manual Handling: Please ensure sufficient & suitable resource / handling aids are used to manage this uplift. LSH employees / representatives will not be able to assist.
67	Wooden topped metal framed workbench with vice 140cm x 75cm x 90cm Please Note:Manual Handling: Please ensure sufficient & suitable resource / handling aids are used to manage this uplift. LSH employees / representatives will not be able to assist.
69	Inspection table with power supply 73cm x 80cm x 142cm Please Note:Manual Handling: Please ensure sufficient & suitable resource / handling aids are used to manage this uplift. LSH employees / representatives will not be able to assist.
73	Mobile metal fabricated trolley Please Note: Manual Handling: Please ensure sufficient & suitable resource / handling aids are used to manage this uplift. LSH employees / representatives will not be able to assist.
75	Wooden topped workbench 140cm x 75cm x 90cm Please Note: Manual Handling: Please ensure sufficient & suitable resource / handling aids are used to manage this uplift. LSH employees / representatives will not be able to assist.
87	Metal double door cabinet